

## Under Review Notification

**Raised By:** Steven Drouin

**Product #:** RBBP1425-101

**Date:** 19.11.28

**Product Name:** INPUT DRIVE SHAFT TOOL KIT

Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143) (eg. RBEM324U3010101-1)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	"Y" or "N" Required for Each Part Do not leave blank								Reserved ECN / URF Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
		DO NOT SHIP	Red Tag/Quarantine Stock	Advise Customers	Hold all Production	Quarantine Tooling (Jigs, Fixtures, etc.)	Re-Work Stock	IPP Under Review (Engineer Signoff Required.)	Put Product Specifications Under Review ("Bluefiles")		
RBBP1425-103/105	RBBP1425-101 Rev. D	Y	Y	N	Y	N	Y	Y	Y	19-1302	Drawing Update
RBBP1425-101	RBBP1425-101 Rev. D									19-1302	

**Description of Issue:**

Customer complaint: Product failing in service Ref : CAR 19-355

Investigation needs to be done on RBBP1425-107/109,  
Probable cause length of RBBP1425-103-05 Guide , and crimping length on total part

<b>Distribution:</b>	VP Operations	Director of Engineering	Customer Support Manager	Technical Support
	Director of Operations	Chief Engineer	Production Engineers	Product Manager - Solutions Provider
	Director Quality Assurance	Engineering Project Managers	Production Planners	Supply Chain Director / Senior Buyer
	QC Coordinator	Engineering Clerk	Purchasing Manager	Marketing Eugene